






VOLVO
Genuine Parts
PV 520 43876
(111:5)

A							REPAIR KITS VACUUM PUMP SERVO CYLINDER						REPARATIONSSATS VAKUUMPUMP SERVOCYLINDER						Group Grupp	
B																			52	
C																			Page Sida	
D																				
E													767							
Fig	Part No. Artikel nr	Quantity / Antal					P S	Description	Benämning	Notes Anmärkning	S R									
		A	B	C	D	E														
1	272722-0	1	-	-	-	-		Repair kit replacement of seals	Reparationssats byte av tätningselement			3								
2	272723-8	1	-	-	-	-		Repair kit replacement of valves	Reparationssats byte av ventiler			3								
3	270596-0	1	-	-	-	-		Valve kit	Ventilsats			2								