



VOLVO
Genuine Parts
LV 237 53732

A			FÖRGASARE REPARATIONSSATS		CARBURETTOR REPAIR KITS		Grupp				
							Group				
							23				
							Sida				
							Page				
B							93				
C											
D											
E											
Pos	Artikel nr Part No.	Antal /Quantity					P S	Benämning	Description	Anmärkning Notes	S R
		A	B	C	D	E					
1	276307-6	1	-	-	-	-	·	Reparationssats	Repair kit	FOR 237627	1
	190349-1	1	-	-	-	-	·	Packning	Gasket		2
	237491-6	1	-	-	-	-	·	Packning	Gasket		2
	237498-1	1	-	-	-	-	·	Packning	Gasket		2
	237504-6	1	-	-	-	-	·	O-ring	O-ring		2
	237506-1	1	-	-	-	-	·	Gummiring	Rubber ring		2
	419568-1	3	-	-	-	-	·	Gummiring	Rubber ring	(237510)	2
	237527-7	1	-	-	-	-	·	O-ring	O-ring		2
	237528-5	1	-	-	-	-	·	Packning	Gasket		2
	418754-8	1	-	-	-	-	·	Packning	Gasket		2
	684812-1	1	-	-	-	-	·	Packning	Gasket		2

☆

