


1



VOLVO
Genuine Parts
LV 882 53073

A			BILBÄLTE FRÄMRE		FRONT SEAT BELT		Grupp				
	B			FRAMSTOL		FRONT SEAT		88			
		C					Sida				
			D					Page			
				E					525		
Pos	Artikel nr Part No.	Antal /Quantity					P. S	Benämning	Description	Anmärkning Notes	S R
		A	B	C	D	E					
1		2	-	-	-	-	NS	Bilbälte	Seat belt	COMPL	
2	1567100-1	1	-	-	-	-		• Bilbälte	• Seat belt		4
3	943395-4	3	-	-	-	-		• Skruv	• Screw		2
4	955896-6	3	-	-	-	-		• Bricka	• Washer		2
5	682437-9	3	-	-	-	-		• Distansrör	• Spacer tube		4
6	944633-7	3	-	-	-	-		• Bricka	• Washer		2
7	943394-7	1	-	-	-	-		• Skruv	• Screw		2
8	942357-5	1	-	-	-	-		• Bricka	• Washer		2
9	672075-9	2	-	-	-	-		• Bussning	• Bushing		3
10	672818-2	1	-	-	-	-		• Distansrör	• Spacer tube		4
11	947049	1	-	-	-	-	NS	• Bricka	• Washer		