



VOLVO
KA 8587



Sida		Grupp		Vindrutespolare		Windscreen washer		Illustration Utgåva	
34		3						4	
Page		Group						8587 Issue	
Pos.	Antal/Quantity			Detalj nr	Benämning	Description	Sats	Anmärkning	
Fig.	673	683		Part No			Kit	Notes	
1	1	-	-	673545-0	Vindrutespolare	Windscreen washer	8	MEAB	010
2	-	1	-	683903-9	Vindrutespolare	Windscreen washer	8	MEAB	020
3	1	-	-	673544-3	•Pump med motor	•Pump with motor		182 CH-30492	030
								ERS AV 688400-1	031
		1	-	688400-1	•Pump med motor	•Pump with motor		182 CH 30493-. 183	040
5	1	-	-	673424-8	••Pump	••Pump	2		050
6	-	1	-	687251-9	••Pump	••Pump	2		060
7	1	1	-	687252-7	••Medbringare	••Companion flange	1	(672737)	070
8	-	1	-	687254-3	••Topplock	••Cover			080
9	1	1	-	671723-5	•Behållare	•Retainer	2		090
10	1	-	-	672408-2	Konsol	Bracket	3	5) VST	10
11	3	-	-	955137-5	Skruv	Screw	0	5) VST	110
12	1	1	-	683487-3	Korg	Basket		14) VST	120
13	3	3	-	955137-5	Skruv	Screw		14) VST	130
14	1225	-	-	943727-8	Slang	Hose		5) VST (192581)	140
	425	600	-	943727-8	Slang	Hose		14) VST	150
	775	950	-	943727-8	Slang	Hose			16
15	1	1	-	347490-5	Korg	Basket	3	HST	170
16	3	3	-	950020-8	Skruv	Screw	0	HST	180
17	3	3	-	940092-0	Mutter	Nut		HST	190
18	2	2	-	665038-6	Gummibussning mellanbräda	Rubber bushing firewall			200
19	1	1	-	659248-9	T-förskruvning	T-union	3		210
20	70	70	-	943722-9	Slang	Hose	1	(192580)	220
	610	610	-	943722-9	Slang	Hose	1	(192580)	230
21	2	2	-	668066-4	Munstycke	Jet	2		240
22	2	2	-	665334-9	•Gummibricka	•Rubber washer	3		250
23	2	2	-	668067-2	•Mutter	•Nut			260
24	3	3	-	192248-3	Klammer	Clamp	0		270
25	1	1	-		Strömställare	Switch		SE SIDA 36	280
									290

5) 182 ch -30000.

14) 182 ch 30001- 183