

VOLVO		PV 445			Grupp Group	3	
Reservdelskatalog Parts catalogue		Instrument 88181	Instrument 88181	Utgåva Issue	1	Sida Page	73
Pos Fig.	Antal Qty.	Benämning	Description	Det. nr Part No.	Anmärkning Notes		
1	1	Instrument, km-indelat, kompl.	Comb. instr. (km.), cpl.	88181			
1	1	. Käpa	. Casing	88665			
2	1	. Glas	. Glass	88666			
3	1	. Glas	. Glass	88667			
4	1	. Glas	. Glass	88668			
5	1	. Hastighetsmätare, kompl.	. Speedometer, cpl.	88621			
6	1	. . Käpa	. . Casing	S.E.S.			
7	1	. . Gummipackning	. . Rubber packing	88623			
8	2	. . Skruv	. . Screw	950011			
9	2	. . Gummibricka	. . Rubber washer	83967			
10	2	. . Bricka	. . Washer	83966			
11	2	. Skruv	. Screw	14172			
12	2	. Monteringsplatta	. Mounting plate	88624			
13	1	. Amperemätare	. Ammeter	88625			
14	1	. Isolerplatta	. Insulating plate	83958			
15	2	. Mutter	. Nut	151214			
16	2	. Lösbricka	. Lock washer	951693			
17	1	. Oljemanometer	. Oil pressure gauge	88627			
18	1	. Bensinmätare	. Fuel gauge	88628			
19	1	. Isolerplatta	. Insulating plate	83962			
20	1	. Mutter	. Nut	151214			
21	1	. Mutter	. Nut	151006			
22	2	. Lösbricka	. Lock washer	951693			
23	1	. Temperaturmätare	. Temperature gauge	88629			
24	1	. Nippel	. Nipple	16212			
25	8	. Skruv	. Screw	14172			

